How can I figure a dimension with[..]

05/18/2024 14:31:58

FAQ Article Print

Category:	FAQ in English::KOMPAS-3D FAQ::Modelling and editing operations FAQ	Last update:	07/04/2008 17:34:49
State:	public (all)		

Keywords

dimension, zero, leader, shelf

Problem (public)

How can I figure a dimension with zero length of shelf leader?

Solution (public)

"Auto create" mode should be disabled when dimensioning. After shelf start point is set in dimension parameters, "Leader Length" field would be available; enter zero valuation in this field.