

Impossible to remove branching[...]

07/16/2024 19:37:45

FAQ Article Print

Category:	FAQ in English::KOMPAS-3D FAQ::Modelling and editing operations FAQ	Last update:	07/04/2008 17:32:03
State:	public (all)		

Keywords

branching

Problem (public)

Impossible to remove branching during editing form tolerance

Solution (public)

Select with the cursor a point of the branching exit from the tolerance table (the point becomes green) in tolerance editing mode, push "Delete" button on the keyboard, push "Create object" button.